



CAUTION

- 1) Ensure that the rope is of sufficient strength to lift 4000 Kgs approx.
- 2) Ensure that during slinging, the ropes do not touch any machine Parts including sheet metal items to avoid damage to them.
- 3) Ensure that Milling Head is resting over the frame and resting block
- 4) Remove all Axis locks, Brackets and Resting Frame, before energising the machine.

BFW

MACHINE LIFTING

XTRON-544