



⚠ CAUTION

- 1) Lower the Milling Head as shown.
- 2) Ensure that the rope is of sufficient strength to lift 10000 kgf.
- 3) Ensure that during slinging, the ropes do not touch any Machine Parts including sheet Metal items to avoid damage to them.
- 4) Remove all Axis locks, Brackets , Resting frame before energizing the machine.