


BMV45+ Machine Lifting Diagram



- 1) Lower the Milling Head as shown.
- 2) Ensure that the rope is of sufficient strength to lift 6000 kgf.
- 3) Ensure that during slinging, the ropes do not touch any Machine Parts including sheet Metal items to avoid damage to them.